



MERCEDES CLA: 2BTB721

Vinnumber:	W1K1183841N296928	Versionname:	CLA CLA 180 Business Solution Essential
First Registrationdate:	14/03/2022	Fiscalpower:	100kW/136pk 4D/P Man-6
Expertise Mileage:	74313	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c523
Fueltype:	Petrol		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
GPS storage		Rear parking sensors	
GPS storage	HD		
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 60 / 16 / 92 / V / Aluminium	5,0 mm	Uniroyal	Summer
	Right	205 / 60 / 16 / 92 / V / Aluminium	5,0 mm	Uniroyal	Summer
Rear	Left	205 / 60 / 16 / 92 / V / Aluminium	5,0 mm	Pirelli	Summer
	Right	205 / 60 / 16 / 92 / V / Aluminium	5,0 mm	Pirelli	Summer

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable



Seat cover R, Stain, Cleaning



Grille, Scratch(es), Acceptable



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Step L, Dent(s), Acceptable



Door FL, Scratch(es), Acceptable



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Acceptable



Mirror side repeater R, Broken, Replace




Outside rear-view mirror housing R, Scratch(es), Smart repair



Wing RR, Scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

