



SEAT Ateca: 2CBM588

Vinnnumber:	VSSZZZ5FZN6537426	Versionname:	Ateca 1.0 TSI Move 81kW/110pk 5D/P Man-6
First Registrationdate:	23/05/2022	Fiscalpower:	
Expertise Mileage:	71073	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	d207
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio
Number keys remote:	2	Front parking sensors
Windows electric F:		Rear parking sensors
Windows electric R:		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Alarm		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

215/55/17/98 V				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 98 V
Tyre size FR				215/55 R 17 98 V
Tyre size RL				215/55 R 17 98 V
Tyre size RR				215/55 R 17 98 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		

Instrument panel, complete, Repaired, Acceptable



Seat cover FR, Stain, Cleaning



Bumper grille, Scratch(es), Acceptable




Windscreen, Stone chip(s), Acceptable



Wing FL, Scratch(es), Polish



Door FL, Scratch(es), Polish



Alloy rim FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door trim FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable




Internal boot lining L, Scratch(es), Smart repair



Bumper trim R, Scratch(es), Smart repair



Alloy rim FR, Scratch(es), Acceptable



Wing FR, Dent(s), Spot repair



Door FR, Dent(s), Acceptable



Door RR, Dent(s), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical pollution, Polish

