



OPEL Corsa: 2DDZ652

Vinnnumber:	VXKUPHNSSN4432597	Versionname:	Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk
First Registrationdate:	17/02/2023	Fiscalpower:	5D/P Auto-8
Expertise Mileage:	11384	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	d254
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Airco manual			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

		195/55/16/91 V			
Summer tyres:	Fr.L.	Other: 7 mm	Fr.R.	Other: 7 mm	
	Re.L.	Other: 7 mm	Re.R.	Other: 7 mm	
Tyre profile depth FL				7.0	
Tyre profile depth FR				7.0	
Tyre profile depth RL				7.0	
Tyre profile depth RR				7.0	
Tyre size FL				195/55 R 16 91 V	
Tyre size FR				195/55 R 16 91 V	
Tyre size RL				195/55 R 16 91 V	
Tyre size RR				195/55 R 16 91 V	
Tyre type FL				All seasons	
Tyre type FR				All Seasons	
Tyre type RL				All seasons	
Tyre type RR				All Seasons	
Tyre make FL				263	
Tyre make FR				263	
Tyre make RL				263	
Tyre make RR				263	


Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bumper F, Bad repair, Spot repair




Roof pillar L, Bad repair, Spot repair



Tailgate / Boot, Bad repair, Spot repair




Rear spoiler, Bad repair, Spot repair



Bumper R, Bad repair, Spot repair



Door RR, Dent(s), Paintless dent repair



Roof pillar R, Bad repair, Spot repair



Roof, Repaired, Acceptable

