

MERCEDES A-Klasse Limousine: 2DCA988

Vinnnumber:	W1K3G8GB9PJ394896	Versionname:	A-Klasse Limousine A 250 e Business Line (PHEV)
First Registrationdate:	31/01/2023	Fiscalpower:	160kW/218pk 4D/P Auto-7
Expertise Mileage:	39733	Power Kw:	118
Bodytype:	Automatic	Body colour:	Black
Gearbox:	Back	Type of rims (mounted):	Aluminium
Transmission:	Back	Parking lot:	PP46
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio	
Number keys remote:	2	Front parking sensors	
GPS storage:		Rear parking sensors	
GPS storage:	HD		
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

205/55/17/95 V				
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL:				6.0
Tyre profile depth FR:				6.0
Tyre profile depth RL:				6.0
Tyre profile depth RR:				6.0
Tyre size FL:				205/55 R 17 95 V
Tyre size FR:				205/55 R 17 95 V
Tyre size RL:				205/55 R 17 95 V
Tyre size RR:				205/55 R 17 95 V
Tyre type FL:				All seasons
Tyre type FR:				All Seasons
Tyre type RL:				All seasons
Tyre type RR:				All Seasons
Tyre make FL:				265
Tyre make FR:				265
Tyre make RL:				261
Tyre make RR:				261


Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		

Instrument panel, complete, Repaired, Acceptable



Windscreen, Stone chip(s), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)



Engine insulation, Missing, Check



Outside rear-view mirror housing L, Scratch(es), Polish



Alloy rim FL polished, Scratch(es), Acceptable




Wing FL, Scratch(es), Polish




Door FL, Dent(s), Spot repair



Step L, Dent(s) and scratch(es), Spot repair



Wing RL, Dent(s), Acceptable



Tailgate / Boot, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Polish



Roof, Dent(s), Acceptable



Bodywork, No damage, Acceptable



Bodywork, No damage, Acceptable

