



MERCEDES A-Klasse: 2BPY331

Vinnnumber:	W1K1770861V121770	Versionname:	A-Klasse A 250 e Business Solution (PHEV)
First Registrationdate:	9/02/2022	Fiscalpower:	160kW/218pk 5D/P Auto-8
Expertise Mileage:	22149	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	a408
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

205/55/16/91 W				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 91 W
Tyre size FR				205/55 R 16 91 W
Tyre size RL				205/55 R 16 91 W
Tyre size RR				205/55 R 16 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		

Instrument panel, complete, Repaired, Acceptable



Steering wheel, Worn, Acceptable



Central pillar L, Dent(s) and scratch(es), Spot repair



Side window trim FL, Scratch(es), Acceptable



Bumper R, Scratch(es), Polish




Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish



Wing RR, Dent(s), Acceptable



Bodywork, No damage, Acceptable

