



PEUGEOT 3008: 1YXT485

Vinnnumber:	VF3MCYHZMLS291920	Versionname:	3008 1.5 BlueHDi S/S Allure Pack 96kW/130pk
First Registrationdate:	25/01/2021	Fiscalpower:	5D/P Man-6
Expertise Mileage:	108008	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	d339
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK


Tyres

225/55/18/102 H				
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/55 R 18 102 H
Tyre size FR				225/55 R 18 102 H
Tyre size RL				225/55 R 18 102 H
Tyre size RR				225/55 R 18 102 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				257
Tyre make FR				257
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FL, Deformed / Strained, Acceptable



Backrest cover FL, Worn, Acceptable



Instrument panel, complete, Repaired, Acceptable



Seat cover FR, Stain, Cleaning



Gear shift lever knob, Worn, Acceptable



Bumper moulding F, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Acceptable



Outside rear-view mirror base L, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable




Door RL, Scratch(es), Acceptable




Door trim FL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Smart repair



Alloy rim RR polished, Scratch(es), Repair and paint (complete)




Door RR, Dent(s), Paintless dent repair



Door FR, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing trim FR, Scratch(es), Acceptable



Outside rear-view mirror base R, Scratch(es), Acceptable



Mirror side repeater R, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

