



MERCEDES CLA Shooting Brake: 2AHM429			
Vinnumber:	W1K1186121N214647	Versionname:	CLA Shooting Brake CLA 200 d Business Solution
First Registrationdate:	6/04/2021	Fiscalpower:	110kW/150pk 5D/P Auto-8
Expertise Mileage:	140006	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	b404
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		
Options			
Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			
Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK
Tyres			
Summer tyres:	295/55/17/91 W		
	Fr.L.	Michelin: 2 mm	Fr.R. Michelin: 2 mm
	Re.L.	Pirelli: 3 mm	Re.R. Pirelli: 3 mm
Tyre profile depth FL			2.0
Tyre profile depth FR			2.0
Tyre profile depth RL			3.0
Tyre profile depth RR			3.0
Tyre size FL			295/55 R 17 91 W
Tyre size FR			295/55 R 17 91 W
Tyre size RL			295/55 R 17 91 W
Tyre size RR			295/55 R 17 91 W
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			261
Tyre make FR			261
Tyre make RL			264
Tyre make RR			264
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		

Number of charging cables (rapid charge)

0

Instrument panel, complete, Repaired, Acceptable






Ignition key, Worn, Acceptable





Instrument panel, complete, Not functioning (well), Check




Bumper F, Dent(s) and scratch(es), Repair and paint (complete)




Brand badge F, Broken, Replace




Bonnet, Scratch(es), Polish




Roof pillar L, Dent(s), Paintless dent repair




Bumper R, Scratch(es), Acceptable




Tailgate / Boot, Scratch(es), Acceptable




Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Door FR, Scratch(es), Acceptable



Central pillar R, Dent(s) and scratch(es), Spot repair




Door RR, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Acceptable



Roof pillar R, Dent(s), Paintless dent repair



Bodywork, No damage, Acceptable

