



MERCEDES A-Klasse Limousine: 2EUW674

Vinnnumber:	W1K3G8FB9PJ420169	Versionname:	A-Klasse Limousine A 250 e Business Line (PHEV)
First Registrationdate:	5/02/2024	Fiscalpower:	160kW/218pk 4D/P Auto-7
Expertise Mileage:	14889	Power Kw:	120
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	a304
Fueltype:	Hybrid Petrol		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Front parking sensors:	
GPS storage:		Rear parking sensors:	
GPS storage:	HD		
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Transmission:	OK
Exhaust gass:	OK		

Tyres

205/55/17/96 V				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL:				6.0
Tyre profile depth FR:				6.0
Tyre profile depth RL:				6.0
Tyre profile depth RR:				6.0
Tyre size FL:				205/55 R 17 96 V
Tyre size FR:				205/55 R 17 96 V
Tyre size RL:				205/55 R 17 96 V
Tyre size RR:				205/55 R 17 96 V
Tyre type FL:				All seasons
Tyre type FR:				All Seasons
Tyre type RL:				All seasons
Tyre type RR:				All Seasons
Tyre make FL:				261
Tyre make FR:				261
Tyre make RL:				261
Tyre make RR:				261


Assistance equipment

Repair kit:	Yes	Compressor:	Yes
-------------	------------	-------------	------------


Number of charging cables (normal)
Number of charging cables (rapid charge)

1
1

Instrument panel, complete, Repaired, Acceptable



Bumper F, Scratch(es), Repair and paint (complete)




Bumper moulding F, Broken, Replace




Door RL, Dent(s) and scratch(es), Spot repair




Wing RL, Dent(s), Spot repair



Door FL, Scratch(es), Acceptable



Bumper R, Dent(s) and scratch(es), Spot repair




Door RR, Scratch(es), Polish





Door FR, Dent(s) and scratch(es), Spot repair




Outside rear-view mirror housing R, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Wing RR, Dent(s), Spot repair



Bodywork, No damage, Acceptable



Bodywork, Missing, Replace

