



VOLVO XC40: 1WBD051

Vinnnumber:	YV1XZ72VDK2150864	Versionname:	XC40 DIESEL 2.0 D3 Inscription Geartronic
First Registrationdate:	11/04/2019	Fiscalpower:	110kw/150pk 5D/P 18
Expertise Mileage:	98132	Power Kw:	
Bodytype:		Body colour:	Brown
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	a410
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Lining leather
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		Fog lights (front)
Steering wheel multifunctional		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

235/55/18/100 V				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/55 R 18 100 V
Tyre size FR				235/55 R 18 100 V
Tyre size RL				235/55 R 18 100 V
Tyre size RR				235/55 R 18 100 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable




Armrest, Hole, Smart repair



Ignition key, Worn, Acceptable



Bonnet, Chemical polution, Polish



Alloy rim FL polished, Scratch(es), Acceptable



Door FL, Dent(s), Acceptable




Alloy rim RL polished, Chemical polution, Polish



Boot cover, Broken, Replace



Tailgate / Boot, Bad repair, Repair and paint (complete)





Rear light L, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Acceptable



Roof pillar R, Bad repair, Spot repair



Door RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Bodywork, Chemical pollution, Polish

