



HYUNDAI Tucson: 2EQL764

Vinnnumber:	TMAJD812DPJ246803	Versionname:	Tucson 1.6 T-GDi Plug-in Hybrid 4x4 Feel (PHEV)
First Registrationdate:	21/12/2023	Fiscalpower:	195kW/265pk 5D/P Auto-6 - CO2 incomplet
Expertise Mileage:	154461	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	4 Wheel-drive	Parking lot:	c124
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Lining leather:	
Windows electric F:		Front parking sensors:	
Windows electric R:		Rear parking sensors:	
Cruise Control:		Fog lights (front):	
Steering wheel multifunctional:			
Seats F heated:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 50 / 19 / 103 / V / Aluminium	4,0 mm	Goodyear	Summer
	Right	235 / 50 / 19 / 103 / V / Aluminium	4,0 mm	Goodyear	Summer
Rear	Left	235 / 50 / 19 / 103 / V / Aluminium	4,0 mm	Goodyear	Summer
	Right	235 / 50 / 19 / 103 / V / Aluminium	5,0 mm	Goodyear	Summer

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	1		

Instrument panel, complete, Repaired, Acceptable



Bumper spoiler F, Scratch(es), Acceptable



Bumper moulding F, Scratch(es), Acceptable



Bonnet, Dent(s), Acceptable




Windscreen, Crack, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Step L, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Polish



Door trim RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Rear window, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Acceptable




Wing FR, Scratch(es), Polish




Door FR, Repaired, Acceptable



Roof pillar R, Dent(s), Acceptable



Step R, Dent(s) and scratch(es), Spot repair



Door RR, Scratch(es), Polish



Wing RR, Scratch(es), Polish



Door trim RR, Deformed / Strained, Replace



Bodywork, No damage, Acceptable



Roof, Scratch(es), Touch up

