



PEUGEOT 208: 2AVS113

Vinnnummer:	VR3UHZKXZMT025965	Versionname:	208 e-208 Allure Pack 100kW/136pk 5D/P Auto-1
First Registrationdate:	6/08/2021	Fiscalpower:	
Expertise Mileage:	15571	Power Kw:	
Bodytype:		Body colour:	Yellow
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c316
Fueltype:	Electric		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	1	Radio:	1
Number keys remote:	1	Rear parking sensors:	1
GPS storage:			
GPS storage:	HD		
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Airco functioning:	Yes	Transmission:	OK
Engine startingtime:	OK		

Degree of wear

195/55/16/87 H				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL:				6.0
Tyre profile depth FR:				6.0
Tyre profile depth RL:				6.0
Tyre profile depth RR:				6.0
Tyre size FL:				195/55 R 16 87 H
Tyre size FR:				195/55 R 16 87 H
Tyre size RL:				195/55 R 16 87 H
Tyre size RR:				195/55 R 16 87 H
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				261
Tyre make FR:				261
Tyre make RL:				261
Tyre make RR:				261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
-------------	------------	-------------	------------

Number of charging cables (normal)
Number of charging cables (rapid charge)

1
1

Ignition key, Missing, Replace



Alloy rim FL, Scratch(es), Repair and paint (complete)



Door FL, Dent(s), Paintless dent repair



Luggage compartment cover, Incomplete, Forfeit



Bumper R, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)





Wing RR, Dent(s), Acceptable

