



VOLVO XC40: 2BQU240

Vinnnummer:	YV1XZBWVFN2750075	Versionname:	XC40 T4 Recharge Geartronic Inscription Expr. (PHEV) 155kW/211pk 5D/P Auto-7
First Registrationdate:	17/02/2022	Fiscalpower:	
Expertise Mileage:	92257	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	a208
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

	235/55/18/104 H			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm
Tyre profile depth FL:				4.0
Tyre profile depth FR:				4.0
Tyre profile depth RL:				3.0
Tyre profile depth RR:				3.0
Tyre size FL:				235/55 R 18 104 H
Tyre size FR:				235/55 R 18 104 H
Tyre size RL:				235/55 R 18 104 H
Tyre size RR:				235/55 R 18 104 H
Tyre type FL:				Winter
Tyre type FR:				Winter
Tyre type RL:				Winter
Tyre type RR:				Winter
Tyre make FL:				256
Tyre make FR:				256
Tyre make RL:				255
Tyre make RR:				255


Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		


Instrument panel, complete, Repaired, Acceptable



Bumper moulding F, Scratch(es), Replace and paint




Bonnet, Dent(s), Acceptable





Wing RL, Dent(s), Spot repair




Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Acceptable




Rear light L, Scratch(es), Polish



Rear spoiler, Chemical polution, Polish




Door FR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable





Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

