


PEUGEOT 508 SW: 2BKA626

Vinnnumber:	VR3F4DGZTMY538173	Versionname:	508 SW 1.6 Hybrid 225 e-EAT8 Allure Pack (PHEV)
First Registrationdate:	15/12/2021	Fiscalpower:	165kW/225pk 5D/P Auto-8
Expertise Mileage:	33809	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	pp95
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	6		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio
Number keys remote:	2	Front parking sensors
Windows electric F:		Rear parking sensors
Windows electric R:		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

215/55/17/98 W				
Summer tyres:	Fr.L.	Vredestein: 1 mm	Fr.R.	Vredestein: 1 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm
Tyre profile depth FL				1.0
Tyre profile depth FR				1.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				215/55 R 17 98 W
Tyre size FR				215/55 R 17 98 W
Tyre size RL				215/55 R 17 98 W
Tyre size RR				215/55 R 17 98 W
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		


Seat cover FL, Worn, Acceptable



Instrument panel, complete, Repaired, Acceptable



Bumper F, Scratch(es), Acceptable




Bonnet, Scratch(es), Polish




Windscreen, Scratch(es), Polish



Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Tyre FL, Worn, Acceptable



Step L, Scratch(es), Acceptable




Alloy rim RL polished, Scratch(es), Acceptable



Door window RL, Scratch(es), Polish



Bumper R, Scratch(es), Polish



Bumper moulding R, Scratch(es), Acceptable




Door FR, Scratch(es), Acceptable




Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Acceptable



Roof pillar R, Scratch(es), Acceptable



Door window RR, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Acceptable



Tyre FR, Worn, Acceptable



Bodywork, No damage, Acceptable



Roof, Scratch(es), Polish

