



OPEL Corsa: 2CNM991				
Vinnumber:	VXKUPHNSSN4346484	Versionname:	Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk	
First Registrationdate:	28/09/2022	Fiscalpower:	5D/P Auto-8	
Expertise Mileage:	17497	Power Kw:		
Bodytype:		Body colour	Black	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:	Front	Parking lot	Bocht 36	
Fueltype:	Petrol			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Bodywork	Clean			
Interior	Clean			
Options				
Number of keys total	2	Front parking sensors		
Number keys remote	2	Rear parking sensors		
Windows electric F				
Windows electric R				
Cruise Control				
Steering wheel multifunctional				
Seats F heated				
Airco manual				
Rims alloy				
Limited Technical Inspection				
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Transmission	OK	
Tyres				
Summer tyres:	195/55/16/91 V			
	Fr.L.	Other: 7 mm	Fr.R.	Other: 7 mm
	Re.L.	Other: 7 mm	Re.R.	Other: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				195/55 R 16 91 V
Tyre size FR				195/55 R 16 91 V
Tyre size RL				195/55 R 16 91 V
Tyre size RR				195/55 R 16 91 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			

Door panel FL, Scratch(es), Acceptable



Seat cover FL, Stain, Cleaning



Seat cover R, Stain, Cleaning



Seat cover FR, Stain, Cleaning



Door FL, Dent(s), Acceptable



Wing RL, Bad repair, Spot repair



Boot lid covering R, Scratch(es), Smart repair



Bumper R, Bad repair, Spot repair



Central pillar R, Bad repair, Spot repair

