



HYUNDAI Nexo: CDBA330

Vinnnummer:	KMHJ8816FLU009557	Versionname:	Nexo FCEV 1 (Hydrogen) 120kW/163pk 5D/P Auto-1
First Registrationdate:	26/01/2022	Fiscalpower:	
Expertise Mileage:	33322	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	d350
Fueltype:	Electric		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Sun Roof electric	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Fog lights (front)	
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Degree of wear

245/45/19/102 V				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				245/45 R 19 102 V
Tyre size FR				245/45 R 19 102 V
Tyre size RL				245/45 R 19 102 V
Tyre size RR				245/45 R 19 102 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		

Bumper F, Scratch(es), Spot repair



Bumper moulding F, Scratch(es), Smart repair



Bonnet, Dent(s), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable




Wing trim RL, Scratch(es), Acceptable



Door trim RL, Scratch(es), Acceptable



Door trim FL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Outer door handle FL, Scratch(es), Acceptable



Wing trim FL, Scratch(es), Smart repair



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Check



Charging cable (fast), Missing, Check



Internal boot lining R, Scratch(es), Acceptable



Door RR, Bad repair, Check



Door trim RR, Scratch(es), Acceptable



Wing RR, Bad repair, Check



Wing trim RR, Scratch(es), Acceptable

