



MERCEDES GLB: 1YXQ324

Vinnnumber:	W1N2476101W078501	Versionname:	GLB GLB 180 d Business Solution 85kW/116pk
First Registrationdate:	22/01/2021	Fiscalpower:	5D/P Auto-8
Expertise Mileage:	74037	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c617
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

215/65/17/99 H				
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/65 R 17 99 H
Tyre size FR				215/65 R 17 99 H
Tyre size RL				215/65 R 17 99 H
Tyre size RR				215/65 R 17 99 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		

Instrument panel, complete, Not functioning (well), Acceptable



Interior, Stain, Cleaning




Backrest cover RM, Scratch(es), Acceptable




Roof liner, Hole, Smart repair



Bumper F, Scratch(es), Polish



Bonnet, Scratch(es), Polish



Windscreen, Stone chip(s), Acceptable



Door FL, Scratch(es), Acceptable





Central pillar L, Dent(s) and scratch(es), Acceptable




Wing RL, Dent(s) and scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Acceptable




Bumper trim R, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable





Wing trim RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Wing trim FR, Scratch(es), Acceptable



Central pillar R, Dent(s), Acceptable



Step R, Dent(s), Acceptable



Door RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

