



OPEL Corsa: 2CXU411

Vinnnumber:	VXKUPHNSSN4427733	Versionname:	Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk
First Registrationdate:	9/01/2023	Fiscalpower:	5D/P Auto-8
Expertise Mileage:	20131	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	Bocht 52
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Front parking sensors
Number keys remote	2	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Airco manual		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

195/55/16/91 H			
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R. Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R. Goodyear: 6 mm
Tyre profile depth FL			6.0
Tyre profile depth FR			6.0
Tyre profile depth RL			6.0
Tyre profile depth RR			6.0
Tyre size FL			195/55 R 16 91 H
Tyre size FR			195/55 R 16 91 H
Tyre size RL			195/55 R 16 91 H
Tyre size RR			195/55 R 16 91 H
Tyre type FL			All seasons
Tyre type FR			All Seasons
Tyre type RL			All seasons
Tyre type RR			All Seasons
Tyre make FL			259
Tyre make FR			259
Tyre make RL			259
Tyre make RR			259


Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover R, Stain, Cleaning



Bonnet, Dent(s), Paintless dent repair



Wing FL, Bad repair, Spot repair



Bumper R, Bad repair, Spot repair



Door RR, Scratch(es), Polish



Roof, Dent(s), Paintless dent repair

