



PEUGEOT 508 SW: 2CHA648

Vinnumber:	VR3FCYHZTNY573784	Versionname:	508 SW 1.5 BlueHdi 130 S/S EAT8 GT 96kW/130pk 5D/P Auto-8
First Registrationdate:	25/07/2022	Fiscalpower:	
Expertise Mileage:	165865	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c110
Fueltype:	Diesel		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Front parking sensors:	
GPS storage:		Rear parking sensors:	
GPS storage:	HD		
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK


Tyres

235/45/18/98 V				
Winter tyres:	Fr.L.	Fulda: 7 mm	Fr.R.	Fulda: 7 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				235/45 R 18 98 V
Tyre size FR				235/45 R 18 98 V
Tyre size RL				235/45 R 18 98 V
Tyre size RR				235/45 R 18 98 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		

Seat cover FL, Worn, Acceptable



Instrument panel, complete, Repaired, Acceptable



Backrest cover RL, Hole, Smart repair




Seat cover RL, Worn, Acceptable



Bumper F, Scratch(es), Repair and paint (complete)




Bonnet, Scratch(es), Acceptable



Engine insulation, Tear, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Spot repair



Alloy rim FL polished, Scratch(es), Acceptable




Outside rear-view mirror housing L, Scratch(es), Polish



Bumper R, Scratch(es), Repair and paint (complete)







Rear window, Scratch(es), Polish



Boot lid covering R, Scratch(es), Acceptable




Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Spot repair



Wing RR, Dent(s), Acceptable



Roof, Hail damage, Paintless dent repair (hail)



Bodywork, No damage, Acceptable

