



VOLVO XC40: 2BJZ166

Vinnnummer:	YV1XZBWVFN2718374	Versionname:	XC40 T4 Recharge Geartronic R-Design (PHEV)
First Registrationdate:	14/12/2021	Fiscalpower:	155kW/211pk 5D/P Auto-7
Expertise Mileage:	108019	Power Kw:	
Bodytype:		Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	pp36
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Lining leather
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

	235/50/19/103 V			
Winter tyres:	Fr.L.	Firestone: 3 mm	Fr.R.	Firestone: 3 mm
	Re.L.	Firestone: 4 mm	Re.R.	Firestone: 4 mm
Tyre profile depth FL			3.0	
Tyre profile depth FR			3.0	
Tyre profile depth RL			4.0	
Tyre profile depth RR			4.0	
Tyre size FL			235/50 R 19 103 V	
Tyre size FR			235/50 R 19 103 V	
Tyre size RL			235/50 R 19 103 V	
Tyre size RR			235/50 R 19 103 V	
Tyre type FL			Winter	
Tyre type FR			Winter	
Tyre type RL			Winter	
Tyre type RR			Winter	
Tyre make FL			258	
Tyre make FR			258	
Tyre make RL			258	
Tyre make RR			258	

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Instrument panel, complete, Repaired, Acceptable




Backrest cover FR, Scratch(es), Smart repair



Windscreen, Scratch(es), Polish



Bonnet, Chemical polution, Polish



Wing FL, Scratch(es), Acceptable



Door FL, Dent(s), Acceptable



Door RL, Dent(s), Paintless dent repair



Damage Picture - 2


Internal boot lining L, Scratch(es), Acceptable




Tailgate / Boot, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Polish



Outside rear-view mirror housing R, Scratch(es), Polish



Central pillar R, Dent(s) and scratch(es), Spot repair



Door RR, Scratch(es), Polish



Step R, Scratch(es), Acceptable



Wing RR, Scratch(es), Polish



Wing trim RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Chemical pollution, Polish

