


HYUNDAI Tucson: 2AVP682

Vinnumber:	TMAJE812DNJ041859	Versionname:	Tucson 1.6 T-GDi Plug-in Hybrid 4x4 Shine (PHEV)
First Registrationdate:	5/08/2021	Fiscalpower:	195kW/265pk 5D/P Auto-6
Expertise Mileage:	58212	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	4 Wheel-drive	Parking lot:	c404
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Fog lights (front)	
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

235/50/19/105 V				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				235/50 R 19 105 V
Tyre size FR				235/50 R 19 105 V
Tyre size RL				235/50 R 19 105 V
Tyre size RR				235/50 R 19 105 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Ignition key, Worn, Acceptable




Bumper F, Scratch(es), Acceptable



Bonnet, Dent(s), Paintless dent repair



Windscreen, Stone chip(s), Windscreen repair



Door RL, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Bumper R, Dent(s), Acceptable



Tailgate / Boot, Dent(s), Spot repair



Wing RR, Dent(s), Acceptable

