
MERCEDES CLA Shooting Brake: 2CCB002

Vinnumber:	W1K1186101N309721	Versionname:	CLA Shooting Brake CLA 180 d Business Solution Essential 85kW/116pk 5D/P Auto-8
First Registrationdate:	30/05/2022	Fiscalpower:	85
Expertise Mileage:	142127	Power Kw:	Grey
Bodytype:		Body colour	Aluminium
Gearbox:	Automatic	Type of rims (mounted)	b102
Transmission:	Front		
Fueltype:	Diesel	Parking lot	
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
GPS storage		Rear parking sensors
GPS storage	HD	
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airc electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

205/60/16/92 H			
Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
Re.L.	Continental: 5 mm	Re.R.	Continental: 6 mm

Tyre profile depth FL	5.0
Tyre profile depth FR	5.0
Tyre profile depth RL	5.0
Tyre profile depth RR	6.0
Tyre size FL	205/60 R 16 92 H
Tyre size FR	205/60 R 16 92 H
Tyre size RL	205/60 R 16 92 H
Tyre size RR	205/60 R 16 92 H
Tyre type FL	Winter
Tyre type FR	Winter
Tyre type RL	Winter
Tyre type RR	Winter
Tyre make FL	257
Tyre make FR	257
Tyre make RL	256
Tyre make RR	256

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Number of charging cables (normal)
Number of charging cables (rapid charge)

0

0

Seat cover FR, Tear, Replace



Floor covering FL, Burned, Smart repair




Interior covering A pillar L, Burned, Smart repair



Instrument panel, complete, Repaired, Acceptable



Roof liner, Burned, Smart repair



Interior, Stain, Cleaning



Bumper F, Scratch(es), Repair and paint (complete)





Bonnet, Stone chip(s), Acceptable




Windscreen, Stone chip(s), Acceptable



Sill trim L, Scratch(es), Acceptable




Wing RL, Bad repair, Spot repair



Step L, Scratch(es), Acceptable



Shutter / cover R, Missing, Repair/replace (lump sum)



Bumper trim R, Scratch(es), Acceptable



Wing FR, Scratch(es), Repair and paint (complete)






Door FR, Scratch(es), Acceptable



Door RR, Dent(s), Acceptable



Bodywork, No damage, Acceptable

