



**VOLVO XC40: 2BEF982**

Vinnnumber:	<b>YV1XZBWVFN2690978</b>	Versionname:	<b>XC40 T4 Recharge Geartronic Inscription Expr. (PHEV) 155kW/211pk 5D/P Auto-7</b>
First Registrationdate:	<b>20/10/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>22705</b>	Power Kw:	
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>a220</b>
Fueltype:	<b>Hybrid Petrol</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total:	<b>2</b>	Radio
Number keys remote:	<b>2</b>	Sun Roof electric
GPS storage:		Front parking sensors
GPS storage:	<b>HD</b>	Rear parking sensors
Windows electric F:		
Windows electric R:		
Cruise Control:		
Steering wheel multifunctional:		
Navigation with screen:		
Airco electronic:		
Rims alloy:		

**Limited Technical Inspection**

Idle position:	<b>NOT OK</b>	Sound engine:	<b>NOT OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Transmission:	<b>OK</b>

**Tyres**

235/55/18/100 V				
Winter tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>
Tyre profile depth FL				<b>6.0</b>
Tyre profile depth FR				<b>6.0</b>
Tyre profile depth RL				<b>6.0</b>
Tyre profile depth RR				<b>6.0</b>
Tyre size FL				<b>235/55 R 18 100 V</b>
Tyre size FR				<b>235/55 R 18 100 V</b>
Tyre size RL				<b>235/55 R 18 100 V</b>
Tyre size RR				<b>235/55 R 18 104 H</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>256</b>
Tyre make FR				<b>256</b>
Tyre make RL				<b>256</b>
Tyre make RR				<b>256</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		


Instrument panel, complete, Repaired, Acceptable



Windscreen, Stone chip(s), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Polish



Wing RL, Dent(s), Acceptable



Charging cable (normal), Missing, Check



Bumper trim R, Hole, Replace



Door trim FR, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Spot repair



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RR, Scratch(es), Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable



Bodywork, Inspection +, Photo complémentaire

