



VOLVO XC40: 1YWX627

Vinnumber:	YV1XZBWVFM2507011	Versionname:	XC40 T4 Recharge Geartronic Inscription Expr.
First Registrationdate:	11/12/2020	Fiscalpower:	155kW/211pk 5D/P Auto-7
Expertise Mileage:	129064	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	b405
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	3	Radio	
Number keys remote:	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Fog lights (front)	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 55 / 18 / 100 / W / Aluminium	5,0 mm	Pirelli	Summer
	Right	235 / 55 / 18 / 100 / W / Aluminium	5,0 mm	Pirelli	Summer
Rear	Left	235 / 55 / 18 / 100 / W / Aluminium	5,0 mm	Pirelli	Summer
	Right	235 / 55 / 18 / 100 / W / Aluminium	5,0 mm	Pirelli	Summer

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		

Instrument panel, complete, Repaired, Acceptable



Ignition key, Broken, Replace





Ignition key, Worn, Acceptable





Interior, Dirty, Chemical cleaning




Bumper moulding F, Dent(s) and scratch(es), Replace




Bumper F, Scratch(es), Polish




Bumper spoiler F, Scratch(es), Acceptable



Bonnet, Dent(s), Acceptable



Alloy rim FL polished, Scratch(es), Polish




Wing FL, Dent(s), Acceptable



Central pillar L, Dent(s) and scratch(es), Spot repair




Door FL, Dent(s) and scratch(es), Spot repair



Luggage compartment cover, Damaged, Smart repair




Boot lid covering R, Scratch(es), Smart repair



Tailgate gas-filled strut L, Not functioning (well), Check



Tailgate / Boot, Scratch(es), Spot repair




Bumper trim R, Scratch(es), Smart repair




Rear light L, Scratch(es), Polish




Alloy rim FR polished, Scratch(es), Repair and paint (complete)






Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Spot repair



Door RR, Dent(s), Paintless dent repair



Bodywork, No damage, Acceptable

