



MERCEDES A-Klasse Limousine: 2BNW769			
Vinnnumber:	W1K1771861J347462	Versionname:	A-Klasse Limousine A 250e Business Solution (PHEV) 160kW/218pk 4D/P Auto-8
First Registrationdate:	28/01/2022	Fiscalpower:	
Expertise Mileage:	70957	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	b115
Fueltype:	Hybrid Petrol		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		



Options	
Number of keys total:	2
Number keys remote:	2
Windows electric F:	
Windows electric R:	
Cruise Control:	
Steering wheel multifunctional:	
Seats F heated:	
Alarm:	
Navigation with screen:	
Airco electronic:	
Rims alloy:	
Radio:	
Front parking sensors:	
Rear parking sensors:	

Limited Technical Inspection			
Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres			
205/55/17/91 W			
Summer tyres:	Fr.L.	Firestone: 3 mm	Fr.R.
	Re.L.	Continental: 3 mm	Re.R.
Tyre profile depth FL:			3.0
Tyre profile depth FR:			3.0
Tyre profile depth RL:			3.0
Tyre profile depth RR:			3.0
Tyre size FL:			205/55 R 17 91 W
Tyre size FR:			205/55 R 17 91 W
Tyre size RL:			205/55 R 17 91 W
Tyre size RR:			205/55 R 17 91 W
Tyre type FL:			Summer
Tyre type FR:			Summer
Tyre type RL:			Summer
Tyre type RR:			Summer
Tyre make FL:			258
Tyre make FR:			258
Tyre make RL:			256
Tyre make RR:			256

Assistance equipment			
Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	2		

Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Damage Picture - 6

Bonnet, Dent(s), Acceptable



Door RL, Dent(s), Acceptable



Door RL, Scratch(es), Acceptable




Roof pillar L, Dent(s), Acceptable



Bumper trim R, Scratch(es), Smart repair



Bumper R, Scratch(es), Polish




Rear light L, Scratch(es), Polish



Wing FR, Scratch(es), Polish



Roof pillar R, Dent(s), Paintless dent repair



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, No damage, Check

