

SEAT Ateca: 2DHD169

Vinnumber:	VSSZZ5F1P6542843	Versionname:	Ateca 1.0 TSI Move Navi 81kW/110pk 5D/P Man-6 (4 seizoenen Banden) - CO2 indicatief
First Registrationdate:	17/03/2023	Fiscalpower:	
Expertise Mileage:	77063	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	pp41
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	3	Radio
Number keys remote	2	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Alarm		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

215/55/17/98 H				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 98 H
Tyre size FR				215/55 R 17 98 H
Tyre size RL				215/55 R 17 98 H
Tyre size RR				215/55 R 17 98 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable



Interior, Stain, Cleaning



Ignition key, Missing, Replace



Centre console, Scratch(es), Smart repair




Bumper moulding F, Scratch(es), Acceptable



Windscreen, Stone chip(s), Acceptable



Door FL, Dent(s), Acceptable



Door RL, Dent(s) and scratch(es), Spot repair



Roof pillar L, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Rear light L, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Acceptable



Wing FR, Dent(s), Acceptable



Outside rear-view mirror housing R, Broken, Replace and paint



Door FR, Dent(s), Acceptable



Wing RR, Dent(s), Acceptable



Bodywork, No damage, Acceptable



Roof, Dent(s), Acceptable

