


MERCEDES CLA Shooting Brake: 2CTJ393

Vinnnumber:	W1K5M8HB9PN352673	Versionname:	CLA Shooting Brake CLA 200 Luxury Line
First Registrationdate:	21/11/2022	Fiscalpower:	120kW/163pk 5D/P Auto-7
Expertise Mileage:	56212	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	a210
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 45 / 18 / 91 / W / Aluminium	5,0 mm	Bridgestone	Summer
	Right	225 / 45 / 18 / 91 / W / Aluminium	5,0 mm	Bridgestone	Summer
Rear	Left	225 / 45 / 18 / 91 / W / Aluminium	5,0 mm	Bridgestone	Summer
	Right	225 / 45 / 18 / 91 / W / Aluminium	5,0 mm	Bridgestone	Summer


Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Instrument panel, complete, Repaired, Acceptable



Door panel RL, Scratch(es), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)




Alloy rim FL polished, Scratch(es), Polish




Mirror side repeater L, Scratch(es), Polish



Door FL, Dent(s), Paintless dent repair



Step L, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Roof pillar R, Dent(s), Paintless dent repair



Wing RR, Dent(s), Paintless dent repair



Alloy rim RR polished, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

