



OPEL Grandland X: 2ACV089			
Vinnumber:	W0VZ45GB5MS018879	Versionname:	Grandland X 1.6 Turbo S/S E-AT8 /ch 4WD Ultim
First Registrationdate:	23/02/2021	Fiscalpower:	221kW/301pk 5D/P Auto-8
Expertise Mileage:	62525	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	N/A
Transmission:	Front	Parking lot	c616
Fueltype:	Hybrid Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	N/A		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options			
Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Fog lights (front)	
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Degree of wear				
	205/55/19/97 H			
Winter tyres:	Fr.L.	Semperit: 4 mm	Fr.R.	Semperit: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 19 97 H
Tyre size FR				205/55 R 19 97 H
Tyre size RL				205/55 R 19 97 V
Tyre size RR				205/55 R 19 97 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				247
Tyre make FR				247
Tyre make RL				25
Tyre make RR				25

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		


Bumper F, Scratch(es), Polish



Alloy rim RL polished, Scratch(es), Acceptable



Wing RL, Scratch(es), Polish



Door FL, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Polish



Bumper R, Scratch(es), Polish



Bumper moulding R, Scratch(es), Smart repair



Wheel arch cover FR. Deformed / Strained. Replace




Alloy rim FR polished, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable




Outside rear-view mirror base R, Scratch(es), Smart repair



Wing RR, Dent(s), Acceptable



Roof, Hail damage, Paintless dent repair (hail)



Bodywork, Hail damage, Check

