



OPEL Astra Sports Tourer: 2ASQ290

Vinnumber:	W0VBE8EV9M8022511	Versionname:	Astra Sports Tourer 1.5 Turbo D S/S Elegance
First Registrationdate:	1/07/2021	Fiscalpower:	90kW/122pk 5D/P Man-6
Expertise Mileage:	79786	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	a314
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	1	Lining leather	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	NOT OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 16 / 91 / V / Aluminium	4,0 mm	Continental	Summer
	Right	205 / 55 / 16 / 91 / V / Aluminium	4,0 mm	Michelin	Summer
Rear	Left	205 / 55 / 16 / 91 / V / Aluminium	4,0 mm	Michelin	Summer
	Right	205 / 55 / 16 / 91 / V / Aluminium	4,0 mm	Michelin	Summer

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable



Door panel FL, Scratch(es), Smart repair




Bumper moulding F, Bad repair, Check



Bumper F, Bad repair, Check



Wing RL, Dent(s), Spot repair



Door RL, Dent(s), Acceptable




Door FL, Scratch(es), Touch up



Wing FL, Dent(s), Spot repair



Outside rear-view mirror housing L, Scratch(es), Acceptable



Bumper R, Bad repair, Check



Tailgate / Boot, Dent(s), Acceptable



Outside rear-view mirror housing R, Scratch(es), Polish



Door FR, Scratch(es), Touch up



Door FR, Scratch(es), Acceptable



Wing RR, Scratch(es), Polish



Alloy rim RR, Scratch(es), Acceptable



Bodywork, No damage, Check



Roof, Chemical pollution, Polish



Bodywork, No damage, Acceptable

