



## VOLVO XC60: 2CWY616

Vinnumber:	<b>YV1UZK5V4P1289647</b>	Versionname:	<b>XC60 B4 D Core Aut. (Mild Hybrid) 145kW/197pk</b>
First Registrationdate:	<b>30/12/2022</b>	Fiscalpower:	<b>5D/P Auto-8 (4 seizoenen Banden) - CO2 onvolledig</b>
Expertise Mileage:	<b>76618</b>	Power Kw:	
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>c419</b>
Fueltype:	<b>Hybrid Diesel</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

## Options

Number of keys total	<b>2</b>	Radio
Number keys remote	<b>2</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

## Limited Technical Inspection

Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Transmission	<b>OK</b>

## Tyres

<b>235/60/18/107 V</b>				
Summer tyres:	Fr.L.	<b>Vredestein: 5 mm</b>	Fr.R.	<b>Vredestein: 5 mm</b>
	Re.L.	<b>Barum: 5 mm</b>	Re.R.	<b>Barum: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>235/60 R 18 107 V</b>
Tyre size FR				<b>235/60 R 18 107 V</b>
Tyre size RL				<b>235/60 R 18 107 V</b>
Tyre size RR				<b>235/60 R 18 107 V</b>
Tyre type FL				<b>All seasons</b>
Tyre type FR				<b>All Seasons</b>
Tyre type RL				<b>All seasons</b>
Tyre type RR				<b>All Seasons</b>
Tyre make FL				<b>2480</b>
Tyre make FR				<b>2480</b>
Tyre make RL				<b>2478</b>
Tyre make RR				<b>2478</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		


Instrument panel, complete, Repaired, Acceptable



Bumper F, Scratch(es), Polish




Bonnet, Chemical polution, Polish




Alloy rim FL, Scratch(es), Polish




Door FL, Scratch(es), Acceptable



Door RL, Dent(s), Acceptable




Wing RL, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Polish



Wing FR, Chemical pollution, Polish



Door FR, Dent(s) and scratch(es), Spot repair



Door RR, Scratch(es), Polish



Bodywork, No damage, Acceptable



Roof, Chemical pollution, Polish

