



PEUGEOT 308: 2CDY187

Vinnumber:	VR3FPHNPLNY554549	Versionname:	308 1.2 PureTech 110 S/S Active Pack 81kW/110pk 5D/P Man-6
First Registrationdate:	17/06/2022	Fiscalpower:	
Expertise Mileage:	85354	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:	Front	Parking lot	c111
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Airco electronic		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

205/55/16/91 V				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		




Bumper F, Scratch(es), Spot repair




Engine insulation, Damaged, Replace




Wheel cover FL, Scratch(es), Replace




Mirror side repeater L, Crack, Replace



Door FL, Scratch(es), Spot repair



Door RL, Dent(s), Acceptable




Wing RL, Dent(s), Acceptable




Tailgate / Boot, Scratch(es), Acceptable



Rear window, Scratch(es), Polish



Bumper trim R, Scratch(es), Smart repair



Bumper R, Scratch(es), Spot repair



Wing RR, Dent(s), Acceptable



Wheel cover RR, Missing, Replace



Door RR, Scratch(es), Polish



Bodywork, No damage, Acceptable

