



SKODA Kamiq: 2BUY519

Vinnumber:	TMBGR6NW9N3082773	Versionname:	Kamiq 1.0 TSI Clever 81kW/110pk 5D/P Man-6
First Registrationdate:	31/03/2022	Fiscalpower:	
Expertise Mileage:	62296	Power Kw:	81
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c217
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

205/55/17/91 V				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 17 91 V
Tyre size FR				205/55 R 17 91 V
Tyre size RL				205/55 R 17 91 V
Tyre size RR				205/55 R 17 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		

Number of charging cables (rapid charge)

0

Glove box, Scratch(es), Acceptable



Interior, Stain, Cleaning




Instrument panel, complete, Repaired, Acceptable



Interior, Smell, Ozone treatment



Door panel FL, Scratch(es), Acceptable




Bumper F, Scratch(es), Spot repair



Bumper spoiler F, Scratch(es), Spot repair




Bonnet, Repaired, Acceptable




Engine insulation, Damaged, Replace




Door RL, Repaired, Acceptable




Wing FL, Scratch(es), Spot repair




Alloy rim FL, Scratch(es), Acceptable




Door seal FL, Broken, Replace




Bumper R, Scratch(es), Acceptable





Tailgate / Boot, Scratch(es), Polish




Rear spoiler, Scratch(es), Acceptable



Wing RR, Dent(s), Acceptable



Door RR, Dent(s), Acceptable



Step R, Dent(s) and scratch(es), Spot repair



Alloy rim FR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Scratch(es), Polish

