



**PEUGEOT 2008: 2BMV164**

Vinnnumber:	<b>VR3USHNSSMJ916248</b>	Versionname:	<b>2008 1.2 Puretech S/S EAT8 GT Pack 96kW/130pk 5D/P Auto-8</b>
First Registrationdate:	<b>18/01/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>30870</b>	Power Kw:	<b>96</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>c423</b>
Fueltype:	<b>Petrol</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total:	<b>2</b>	Radio:	
Number keys remote:	<b>2</b>	Front parking sensors:	
GPS storage:		Rear parking sensors:	
GPS storage:	<b>HD</b>	Fog lights (front):	
Windows electric F:			
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

**Limited Technical Inspection**

Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Transmission:	<b>OK</b>
Exhaust gass:	<b>OK</b>		

**Tyres**

215/55/18/99 V				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>
Tyre profile depth FL:				<b>5.0</b>
Tyre profile depth FR:				<b>5.0</b>
Tyre profile depth RL:				<b>6.0</b>
Tyre profile depth RR:				<b>6.0</b>
Tyre size FL:				<b>215/55 R 18 99 V</b>
Tyre size FR:				<b>215/55 R 18 99 V</b>
Tyre size RL:				<b>215/55 R 18 99 V</b>
Tyre size RR:				<b>215/55 R 18 99 V</b>
Tyre type FL:				<b>Summer</b>
Tyre type FR:				<b>Summer</b>
Tyre type RL:				<b>Summer</b>
Tyre type RR:				<b>Summer</b>
Tyre make FL:				<b>261</b>
Tyre make FR:				<b>261</b>
Tyre make RL:				<b>261</b>
Tyre make RR:				<b>261</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
-------------	------------	-------------	------------

Number of charging cables (normal)  
Number of charging cables (rapid charge)

0  
0

Instrument panel, complete, Repaired, Acceptable



Engine insulation, Damaged, Replace



Windscreen, Stone chip(s), Acceptable



Bumper F, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Door FL, Dent(s), Acceptable



Door RL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Acceptable



Rear window, Scratch(es), Acceptable




Tailgate / Boot, Scratch(es), Acceptable



Bumper trim R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Replace



Door FR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Wing trim FR, Scratch(es), Replace



Bodywork, No damage, Acceptable

