



MERCEDES EQC: 2BSM227			
Vinnumber:	W1K2938901F041599	Versionname:	EQC EQC 400 4MATIC Business Solution AMG
First Registrationdate:	8/03/2022	Fiscalpower:	300kW/408pk 5D/P Auto-1
Expertise Mileage:	71584	Power Kw:	
Bodytype:		Body colour	White
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	4 Wheel-drive	Parking lot	c226
Fueltype:	Electric		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Dirty		

Options			
Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Sun Roof electric	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres				
235/55/19/105 W				
Summer tyres:	Fr.L.	Firestone: 3 mm	Fr.R.	Firestone: 3 mm
	Re.L.	Firestone: 3 mm	Re.R.	Firestone: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				235/55 R 19 105 W
Tyre size FR				235/55 R 19 105 W
Tyre size RL				235/55 R 19 105 W
Tyre size RR				235/55 R 19 105 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				258
Tyre make RR				258

Assistance equipment			
Number of charging cables (normal)	1	Compressor	No
Number of charging cables (rapid charge)	2		

Centre console, Scratch(es), Acceptable



Floor covering FL, Burned, Smart repair



Roof liner, Burned, Smart repair



Bumper F, Scratch(es), Polish



Bumper moulding F, Scratch(es), Replace



Headlight L, Scratch(es), Polish



Alloy rim FL polished, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Mirror side repeater L, Scratch(es), Polish



Wing RL, Dent(s), Paintless dent repair





Alloy rim RL polished, Scratch(es), Acceptable




Compressor, Missing, Replace



Boot cover, Tear, Smart repair



Boot lid covering R, Scratch(es), Acceptable




Bumper trim R, Scratch(es), Smart repair



Bumper R, Scratch(es), Acceptable



Rear light L, Scratch(es), Polish




Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Mirror side repeater R, Scratch(es), Polish



Outside rear-view mirror base R, Scratch(es), Acceptable



Sill trim R, Scratch(es), Replace



Sill trim R, Scratch(es), Acceptable



Outer door handle RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

