



OPEL Crossland X: 1XMF803

Vinnnumber:	W0V7H9EG5L4130456	Versionname:	Crossland X 1.5 Turbo D S/S Innovation
First Registrationdate:	10/02/2020	Fiscalpower:	75kW/102pk 5D/P Man-6
Expertise Mileage:	79059	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	a317
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	1	Radio
Number keys remote	1	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 60 / 16 / 89 / H / Aluminium	4,0 mm	Bridgestone	Summer
	Right	195 / 60 / 16 / 89 / H / Aluminium	4,0 mm	Bridgestone	Summer
Rear	Left	195 / 60 / 16 / 89 / H / Aluminium	4,0 mm	Bridgestone	Summer
	Right	195 / 60 / 16 / 89 / H / Aluminium	4,0 mm	Bridgestone	Summer

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Ignition key, Missing, Replace



Instrument panel, complete, Repaired, Acceptable



Bumper F, Scratch(es), Polish



Bonnet, Repaired, Acceptable



Wing FL, Scratch(es), Polish



Door FL, Scratch(es), Spot repair



Wing RL, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Acceptable




Rear light L, Scratch(es), Polish



Alloy rim FR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Alloy rim RR, Chemical polution, Polish



Bodywork, No damage, Acceptable



Roof, Scratch(es), Polish

