




OPEL Mokka: 2CLA604

Vinnumber:	VXKUDYHSKNW038992	Versionname:	Mokka 1.5 Turbo D S/S Elegance 81kW/110pk 5D/P Man-6
First Registrationdate:	31/08/2022	Fiscalpower:	
Expertise Mileage:	50007	Power Kw:	
Bodytype:		Body colour	Green
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c212
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Rear parking sensors	
Windows electric F		Fog lights (front)	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 96 / V / Aluminium	6,0 mm	Goodyear	Summer
	Right	215 / 60 / 17 / 96 / V / Aluminium	6,0 mm	Goodyear	Summer
Rear	Left	215 / 60 / 17 / 96 / V / Aluminium	6,0 mm	Goodyear	Summer
	Right	215 / 60 / 17 / 96 / V / Aluminium	6,0 mm	Goodyear	Summer

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable



Seat cover FL, Stain, Cleaning



Shutter / cover F, Deformed / Strained, Replace



Wing RL, Scratch(es), Acceptable




Alloy rim FL polished, Scratch(es), Acceptable



Wing FL, Bad repair, Repair and paint (complete)



Tailgate / Boot, Dent(s), Paintless dent repair



Roof pillar R, Scratch(es), Polish



Bodywork, No damage, Acceptable



Roof, Chemical polution, Polish

