


PEUGEOT 308: 2BWW940

Vinnumber:	VR3FPHNSTNY514510	Versionname:	308 1.2 PureTech 130 S/S EAT8 Allure Pack
First Registrationdate:	25/04/2022	Fiscalpower:	96kW/130pk 5D/P Auto-8
Expertise Mileage:	80784	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	b201
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio
Number keys remote:	2	Front parking sensors
GPS storage:		Rear parking sensors
GPS storage:	HD	
Windows electric F:		
Windows electric R:		
Cruise Control:		
Steering wheel multifunctional:		
Navigation with screen:		
Airco electronic:		
Rims alloy:		

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Transmission:	OK
Exhaust gass:	OK		

Tyres

	225/45/17/94 V			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm
Tyre profile depth FL:				4.0
Tyre profile depth FR:				4.0
Tyre profile depth RL:				5.0
Tyre profile depth RR:				5.0
Tyre size FL:				225/45 R 17 94 V
Tyre size FR:				225/45 R 17 94 V
Tyre size RL:				225/45 R 17 94 V
Tyre size RR:				225/45 R 17 94 V
Tyre type FL:				Winter
Tyre type FR:				Winter
Tyre type RL:				Winter
Tyre type RR:				Winter
Tyre make FL:				265
Tyre make FR:				265
Tyre make RL:				265
Tyre make RR:				265


Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		


Centre console, Scratch(es), Smart repair



Bonnet, Dent(s) and scratch(es), Acceptable



Bumper F, Scratch(es), Spot repair




Step L, Dent(s) and scratch(es), Spot repair



Steel rim RL, Scratch(es), Polish



Door RL, Scratch(es), Polish



Door FL, Scratch(es), Acceptable








Alloy rim FL polished, Scratch(es), Repair and paint (complete)




Tailgate / Boot, Scratch(es), Polish



Bumper R, Scratch(es), Polish




Wing RR, Dent(s) and scratch(es), Acceptable




Outer sill R, Scratch(es), Polish



Door RR, Scratch(es), Acceptable



Door FR, Scratch(es), Spot repair



Outside rear-view mirror housing R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable



Roof, Hail damage, Paintless dent repair (hail)

