



MERCEDES Sprinter: 2CDP850				
Vinnumber:	W1V9106331P462218	Versionname:	Sprinter 311 CDI GB L2 FWD Functional 3.5T	
First Registrationdate:	15/06/2022	Fiscalpower:	84kW/114pk 4D/P Man-6	
Expertise Mileage:	21056	Power Kw:		
Bodytype:		Body colour	Blue	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel	
Transmission:	Front	Parking lot	d110	
Fueltype:	Diesel			
Number of doors	5			
Number of seats	3			
Number head rests	3			
Type of rims (mounted)	Steel			
Certificate of Conformity	Yes			
Category	Light Commercial Vehicle			
Registration Certificate Car (BE)	Yes			
Bodywork	Dirty			
Interior	Clean			
Options				
Number of keys total	2	Radio		
Number keys remote	2			
Windows electric F				
Cruise Control				
Steering wheel multifunctional				
Airco electronic				
Limited Technical Inspection				
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Transmission	OK	
Tyres				
Summer tyres:	225/65/16/110 R			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/65 R 16 110 R
Tyre size FR				225/65 R 16 110 R
Tyre size RL				225/65 R 16 110 R
Tyre size RR				225/65 R 16 110 R
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Instrument panel, complete, Repaired, Acceptable				



Seat cover FL, Broken, Smart repair



Bumper F, Scratch(es), Acceptable




Door FL, Dent(s), Acceptable



Central pillar L, Dent(s) and scratch(es), Spot repair



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RL, Scratch(es), Replace



Roof pillar L, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RL, Dent(s) and scratch(es), Spot repair



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Smart repair



Door FR, Dent(s), Acceptable




Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RR, Missing, Replace



Outer sill R, Rust, Repair and paint (complete)



Wing trim RR, Missing, Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Roof pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Wheel arch cover FR, Broken, Replace



Bodywork, Not original part, Remove lettering



Roof, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable



Bodywork, No damage, Acceptable

