



PEUGEOT 2008: 2BDJ894			
Vinnnumber:	VR3USHNSKMJ822489	Versionname:	2008 1.2 Puretech S/S Allure Pack 96kW/130pk
First Registrationdate:	11/10/2021	Fiscalpower:	5D/P Man-6
Expertise Mileage:	58681	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c321
Fueltype:	Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options			
Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Fog lights (front)	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres				
	215/60/17/96 H			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				3.0
Tyre size FL				215/60 R 17 96 H
Tyre size FR				215/60 R 17 96 H
Tyre size RL				215/60 R 17 96 H
Tyre size RR				215/60 R 17 96 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Bonnet, Dent(s), Acceptable



Engine insulation, Missing, Replace




Door FL, Dent(s), Acceptable




Alloy rim FL polished, Scratch(es), Acceptable



Door RL, Scratch(es), Polish



Tailgate / Boot, Dent(s), Spot repair



Bumper R, Scratch(es), Acceptable



Boot cover, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Spot repair



Bodywork, No damage, Acceptable

