



**VOLVO XC40: 2BGS583**

Vinnnumber:	<b>YV1XZBWVFN2694843</b>	Versionname:	<b>XC40 T4 Recharge Geartronic Inscription Expr. (PHEV) 155kW/211pk 5D/P Auto-7</b>
First Registrationdate:	<b>18/11/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>45339</b>	Power Kw:	
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>b204</b>
Fueltype:	<b>Hybrid Petrol</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total:	<b>2</b>	Radio:	
Number keys remote:	<b>2</b>	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

**Limited Technical Inspection**

Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Transmission:	<b>OK</b>

**Tyres**

<b>235/55/18/100 H</b>				
Winter tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>
Tyre profile depth FL:				<b>4.0</b>
Tyre profile depth FR:				<b>4.0</b>
Tyre profile depth RL:				<b>5.0</b>
Tyre profile depth RR:				<b>5.0</b>
Tyre size FL:				<b>235/55 R 18 100 H</b>
Tyre size FR:				<b>235/55 R 18 100 H</b>
Tyre size RL:				<b>235/55 R 18 100 H</b>
Tyre size RR:				<b>235/55 R 18 100 H</b>
Tyre type FL:				<b>Winter</b>
Tyre type FR:				<b>Winter</b>
Tyre type RL:				<b>Winter</b>
Tyre type RR:				<b>Winter</b>
Tyre make FL:				<b>256</b>
Tyre make FR:				<b>256</b>
Tyre make RL:				<b>256</b>
Tyre make RR:				<b>256</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>1</b>		
Number of charging cables (rapid charge):	<b>1</b>		

Instrument panel, complete, Repaired, Acceptable




Door panel RR, Scratch(es), Acceptable




Centre console, Scratch(es), Acceptable



Bonnet, Scratch(es), Polish



Roof pillar L, Scratch(es), Acceptable



Door RL, Repaired, Acceptable




Step L, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Wing trim RL, Chemical polution, Replace



Wing RL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Polish



Wing FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Repaired, Acceptable



Door FR, Scratch(es), Acceptable




Door RR, Repaired, Acceptable



Wing RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

