



VOLVO XC40: 2BGS583

Vinnnumber:	YV1XZBWVFN2694843	Versionname:	XC40 T4 Recharge Geartronic Inscription Expr. (PHEV) 155kW/211pk 5D/P Auto-7
First Registrationdate:	18/11/2021	Fiscalpower:	
Expertise Mileage:	45339	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	b204
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

235/55/18/100 H				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL:				4.0
Tyre profile depth FR:				4.0
Tyre profile depth RL:				5.0
Tyre profile depth RR:				5.0
Tyre size FL:				235/55 R 18 100 H
Tyre size FR:				235/55 R 18 100 H
Tyre size RL:				235/55 R 18 100 H
Tyre size RR:				235/55 R 18 100 H
Tyre type FL:				Winter
Tyre type FR:				Winter
Tyre type RL:				Winter
Tyre type RR:				Winter
Tyre make FL:				256
Tyre make FR:				256
Tyre make RL:				256
Tyre make RR:				256

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		

Instrument panel, complete, Repaired, Acceptable



Damage Picture - 1


Door panel RR, Scratch(es), Acceptable




Centre console, Scratch(es), Acceptable



Bonnet, Scratch(es), Polish



Roof pillar L, Scratch(es), Acceptable




Door RL, Repaired, Acceptable




Step L, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Wing trim RL, Chemical polution, Replace



Wing RL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Polish



Wing FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Repaired, Acceptable



Door FR, Scratch(es), Acceptable




Door RR, Repaired, Acceptable



Wing RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

