



VOLVO XC40: 2BPK387

Vinnnumber:	YV1XZ15VDN2739830	Versionname:	XC40 T3 Geartronic R-Design 120kW/163pk 5D/P
First Registrationdate:	3/02/2022	Fiscalpower:	Auto-8
Expertise Mileage:	77565	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	a305
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total:	2	Radio	
Number keys remote:	2	Front parking sensors	
Windows electric F:		Rear parking sensors	
Windows electric R:		Fog lights (front)	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	NOT OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

	235/55/18/100 V			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/55 R 18 100 V
Tyre size FR				235/55 R 18 100 V
Tyre size RL				235/55 R 18 100 V
Tyre size RR				235/55 R 18 100 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Instrument panel, complete, Not functioning (well), Check



Instrument panel, complete, Repaired, Acceptable




Bonnet, Chemical polution, Polish



Alloy rim FL polished, Chemical polution, Polish




Door FL, Dent(s), Paintless dent repair




Door RL, Scratch(es), Polish




Outer door handle FL, Scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Rear light R, Scratch(es), Replace



Tailgate / Boot, Scratch(es), Acceptable




Alloy rim FR polished, Scratch(es), Acceptable



Wing FR, Dent(s), Acceptable



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RR, Scratch(es), Replace



Bodywork, No damage, Check



Bodywork, No damage, Check

