



VOLVO XC60: 2ESU333

Vinnnumber:	YV1UZH4V9R1861612	Versionname:	XC60 T6 PHEV 4x4 Ultimate Dark Aut. (PHEV)
First Registrationdate:	16/01/2024	Fiscalpower:	257kW/350pk 5D/P Auto-8 (4 seizoenen Banden) - CO2 onvolledig
Expertise Mileage:	10476	Power Kw:	
Bodytype:		Body colour:	Red
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	4 Wheel-drive	Parking lot:	c206
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Dirty		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Lining leather:	
Windows electric F:		Sun Roof electric:	
Windows electric R:		Front parking sensors:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:			
Seats F heated:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

Limited Technical Inspection

Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Transmission:	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 45 / 20 / 105 / V / Aluminium	4,0 mm	Michelin	All season
	Right	225 / 45 / 20 / 105 / V / Aluminium	4,0 mm	Michelin	All season
Rear	Left	225 / 45 / 20 / 105 / V / Aluminium	4,0 mm	Michelin	All season
	Right	225 / 45 / 20 / 105 / V / Aluminium	4,0 mm	Michelin	All season

Assistance equipment

Number of charging cables (normal):	0	Compressor:	No
Number of charging cables (rapid charge):	1		

Instrument panel, complete, Repaired, Acceptable



Interior, Dirty, Chemical cleaning



Bumper F, Scratch(es), Spot repair



Bonnet, Chemical polution, Polish



Compressor, Missing, Replace



Luggage compartment cover, Missing, Check



Wing FR, Chemical polution, Polish



Outside rear-view mirror housing R, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable

