



VOLVO V60: 2ATD943

Vinnumber:	YV1ZWK6VDN2469381	Versionname:	V60 B3 Geartronic Momentum Pro (Mild Hybrid)
First Registrationdate:	7/07/2021	Fiscalpower:	120kW/163pk 5D/P Auto-8
Expertise Mileage:	40968	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	c427
Fueltype:	Hybrid Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Fog lights (front)	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 50 / 17 / 98 / V / Aluminium	4,0 mm	Michelin	Summer
	Right	225 / 50 / 17 / 98 / V / Aluminium	4,0 mm	Michelin	Summer
Rear	Left	225 / 50 / 17 / 98 / V / Aluminium	4,0 mm	Michelin	Summer
	Right	225 / 50 / 17 / 98 / V / Aluminium	4,0 mm	Michelin	Summer

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Repaired, Acceptable



Interior, Smell, Ozone treatment



Interior, Stain, Cleaning



Bumper F, Scratch(es), Spot repair



Door FL, Scratch(es), Spot repair



Door RL, Scratch(es), Acceptable



Sill trim L, Scratch(es), Repair and paint (complete)



Tailgate gas-filled strut L, Not functioning (well), Check



Bumper R, Scratch(es), Spot repair




Rear light L, Scratch(es), Polish




Door RR, Dent(s), Paintless dent repair



Wing RR, Scratch(es), Spot repair



Alloy rim RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

