



MERCEDES EQA: 2EBC483

Vinnnumber:	W1N9N0JB1RJ087397	Versionname:	EQA EQA 300 4MATIC Luxury Line 168kW/228pk
First Registrationdate:	11/08/2023	Fiscalpower:	5D/P Auto-1 - WLTP onvolledig
Expertise Mileage:	50374	Power Kw:	
Bodytype:		Body colour:	Silver
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	4 Wheel-drive	Parking lot:	c328
Fueltype:	Electric		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

235/55/18/104 H				
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/55 R 18 104 H
Tyre size FR				235/55 R 18 104 H
Tyre size RL				235/55 R 18 104 H
Tyre size RR				235/55 R 18 104 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		


Instrument panel, complete, Repaired, Acceptable



Door FL, Scratch(es), Acceptable




Luggage compartment cover, Damaged, Acceptable



Rear window, Scratch(es), Acceptable



Door FR, Dent(s) and scratch(es), Spot repair



Wing RR, Dent(s), Acceptable



Bodywork, No damage, Acceptable

