


MERCEDES CLA Shooting Brake: 2BRM050

Vinnnumber:	W1K1186861N291344	Versionname:	CLA Shooting Brake CLA 250 e Business Solution (PHEV) 160kW/218pk 5D/P Auto-8
First Registrationdate:	24/02/2022	Fiscalpower:	
Expertise Mileage:	67528	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	c508
Fueltype:	Hybrid Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Sun Roof electric	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK


Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 45 / 18 / 91 / W / Aluminium	4,0 mm	Continental	Summer
	Right	225 / 45 / 18 / 91 / W / Aluminium	4,0 mm	Continental	Summer
Rear	Left	225 / 45 / 18 / 91 / W / Aluminium	4,0 mm	Hankook	Summer
	Right	225 / 45 / 18 / 91 / W / Aluminium	4,0 mm	Hankook	Summer


Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Instrument panel, complete, Repaired, Acceptable



Bumper F, Crack, Replace and paint



Bumper moulding F, Broken, Replace



Bonnet, Chemical polution, Polish




Brand badge F, Broken, Replace




Shutter / cover F, Deformed / Strained, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Central pillar L, Dent(s) and scratch(es), Spot repair



Door FL, Dent(s), Acceptable




Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Wing RL, Dent(s), Acceptable




Bumper moulding R, Crack, Replace




Tailgate / Boot, Dent(s), Paintless dent repair



Rear window, Scratch(es), Replace



Bumper R, Scratch(es), Spot repair



Bumper trim R, Scratch(es), Smart repair



Bumper moulding R, Scratch(es), Replace




Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Polish



Door FR, Dent(s) and scratch(es), Spot repair



Central pillar R, Dent(s) and scratch(es), Spot repair



Door RR, Bad repair, Repair and paint (complete)




Roof pillar R, Bad repair, Repair and paint (complete)



Wing RR, Bad repair, Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Bodywork, No damage, Acceptable

