


SKODA Karoq: 2BMP074

Vinnnumber:	TMBJR7NU0N5028986	Versionname:	Karoq 1.5 TSI DSG7 Clever+ 110kW/150pk 5D/P Auto-7
First Registrationdate:	14/01/2022	Fiscalpower:	
Expertise Mileage:	54603	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	d210
Fueltype:	Petrol		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Clean		
Interior:	Clean		

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Fog lights (front)
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Alarm		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

215/55/17/94 V				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				215/55 R 17 94 V
Tyre size FR				215/55 R 17 94 V
Tyre size RL				215/55 R 17 94 V
Tyre size RR				215/55 R 17 94 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		

Instrument panel, complete, Repaired, Acceptable




Interior, Dirty, Chemical cleaning



Bonnet, Chemical polution, Polish



Door FL, Scratch(es), Acceptable




Outside rear-view mirror housing L, Scratch(es), Acceptable




Wing RL, Scratch(es), Spot repair



Alloy rim RL, Scratch(es), Repair and paint (complete)




Boot lid covering R, Scratch(es), Smart repair



Tailgate / Boot, Dent(s), Spot repair



Door RR, Dent(s), Paintless dent repair



Alloy rim FR, Scratch(es), Repair and paint (complete)




Tyre FR, Tear, Replace



Wing FR, Scratch(es), Spot repair




Door FR, Scratch(es), Spot repair



Roof pillar R, Dent(s), Paintless dent repair



Wing RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable



Roof, Dent(s), Acceptable

