

**OPEL Corsa: 2CKZ396**

Vinnnumber:	<b>VXKUPHNSSN4310531</b>	Versionname:	<b>Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk</b>
First Registrationdate:	<b>31/08/2022</b>	Fiscalpower:	<b>5D/P Auto-8</b>
Expertise Mileage:	<b>19416</b>	Power Kw:	
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Front</b>	Parking lot:	<b>bocht109</b>
Fueltype:	<b>Petrol</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total:	<b>2</b>	Radio
Number keys remote:	<b>2</b>	Front parking sensors
Windows electric F:		Rear parking sensors
Windows electric R:		
Cruise Control:		
Steering wheel multifunctional:		
Seats F heated:		
Airco manual:		
Rims alloy:		

**Limited Technical Inspection**

Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Transmission:	<b>OK</b>

**Tyres**

	<b>195/55/16/91 H</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Other: 3 mm</b>	Re.R.	<b>Other: 3 mm</b>
Tyre profile depth FL:				<b>3.0</b>
Tyre profile depth FR:				<b>3.0</b>
Tyre profile depth RL:				<b>3.0</b>
Tyre profile depth RR:				<b>3.0</b>
Tyre size FL:				<b>195/55 R 16 91 H</b>
Tyre size FR:				<b>195/55 R 16 91 H</b>
Tyre size RL:				<b>195/55 R 16 91 H</b>
Tyre size RR:				<b>195/55 R 16 91 H</b>
Tyre type FL:				<b>All seasons</b>
Tyre type FR:				<b>All Seasons</b>
Tyre type RL:				<b>All seasons</b>
Tyre type RR:				<b>All Seasons</b>
Tyre make FL:				<b>259</b>
Tyre make FR:				<b>259</b>
Tyre make RL:				<b>263</b>
Tyre make RR:				<b>263</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Interior covering A pillar L, Scratch(es), Acceptable




Door FL, Dent(s), Acceptable




Central pillar L, Bad repair, Spot repair



Wing FL, Bad repair, Spot repair



Wing RL, Bad repair, Spot repair



Bumper R, Bad repair, Spot repair



Rear spoiler, Bad repair, Spot repair



Door RR, Bad repair, Spot repair



Roof, Repaired, Acceptable

