



OPEL Corsa: 2CSQ345

Vinnumber:	VXKUPHNSSN4399407	Versionname:	Corsa 1.2 Turbo S/S Auto GS Line 96kW/131pk 5D/P Auto-8
First Registrationdate:	14/11/2022	Fiscalpower:	
Expertise Mileage:	20092	Power Kw:	
Bodytype:		Body colour	
Gearbox:	Automatic	Type of rims (mounted)	Black
Transmission:	Front	Parking lot	Aluminium
Fueltype:	Petrol		bocht 50
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio
Number keys remote		
Windows electric F	2	Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Airco manual		
Rims alloy		

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

195/55/16/91 H					
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm	
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm	
Tyre profile depth FL					6.0
Tyre profile depth FR					6.0
Tyre profile depth RL					6.0
Tyre profile depth RR					6.0
Tyre size FL					195/55 R 16 91 H
Tyre size FR					195/55 R 16 91 H
Tyre size RL					195/55 R 16 91 H
Tyre size RR					195/55 R 16 91 H
Tyre type FL					All seasons
Tyre type FR					All Seasons
Tyre type RL					All seasons
Tyre type RR					All Seasons
Tyre make FL					259
Tyre make FR					259
Tyre make RL					259
Tyre make RR					259


Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Centre console, Glue residues, Cleaning




Door RL, Bad repair, Spot repair



Outside rear-view mirror housing L, Scratch(es), Acceptable



Roof pillar L, Scratch(es), Acceptable




Wing FL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Smart repair



Wing FR, Bad repair, Spot repair



Outside rear-view mirror base R, Scratch(es), Smart repair



Mirror side repeater R, Scratch(es), Polish



Outside rear-view mirror housing R, Scratch(es), Polish



Central pillar R, Bad repair, Spot repair

