



**MERCEDES E-Klasse Break: 2BHE505**

Vinnnumber:	<b>W1K2132041B023708</b>	Versionname:	<b>Classe E Break E 220d Business Solution</b>
First Registrationdate:	<b>24/11/2021</b>	Fiscalpower:	<b>143kW/194pk 5D/P Auto-9</b>
Expertise Mileage:	<b>83649</b>	Power Kw:	
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:	<b>Back</b>	Parking lot:	<b>pp47</b>
Fueltype:	<b>Diesel</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Bodywork:	<b>Clean</b>		
Interior:	<b>Clean</b>		

**Options**

Number of keys total:	<b>2</b>	Radio:	
Number keys remote:	<b>2</b>	Lining leather:	
GPS storage:		Sun Roof electric:	
GPS storage:	<b>HD</b>	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:			
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Navigation with screen:			
Airco electronic:			
Rims alloy:			

**Limited Technical Inspection**

Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Transmission:	<b>OK</b>
Exhaust gass:	<b>OK</b>		

**Tyres**

245/45/18/100 V				
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>
Tyre profile depth FL				<b>4.0</b>
Tyre profile depth FR				<b>4.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>245/45 R 18 100 V</b>
Tyre size FR				<b>245/45 R 18 100 V</b>
Tyre size RL				<b>275/40 R 18 105 V</b>
Tyre size RR				<b>275/40 R 18 105 V</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>261</b>
Tyre make FR				<b>261</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
-------------	------------	-------------	------------

Number of charging cables (normal)  
Number of charging cables (rapid charge)

0  
0

Door panel FR, Worn, Acceptable



Backrest cover FL, Worn, Acceptable




Instrument panel, complete, Repaired, Acceptable



Door panel FL, Worn, Acceptable



Bumper F, Scratch(es), Spot repair



Shutter / cover F, Not functioning (well), Acceptable



Windscreen, Stone chip(s), Windscreen repair



Bonnet, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Step L, Dent(s) and scratch(es), Spot repair




Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Sill trim L, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



A-pillar right, Scratch(es), Acceptable



Step R, Dent(s) and scratch(es), Acceptable



Wing RR, Dent(s), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)





Door RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Bodywork, Not original part, Remove lettering



Bodywork, No damage, Acceptable

