



MERCEDES A-Klasse Limousine: 2DHZ444

Vinnumber:	W1K3G8FB1PJ415127	Versionname:	A-Klasse Limousine A 250 e Business Line (PHEV)
First Registrationdate:	27/03/2023	Fiscalpower:	160kW/218pk 4D/P Auto-7
Expertise Mileage:	25949	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	b314
Fueltype:	Hybrid Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		

Options

Number of keys total	2	Radio	
Number keys remote	2	Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

205/55/17/95 V				
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/55 R 17 95 V
Tyre size FR				205/55 R 17 95 V
Tyre size RL				205/55 R 17 95 V
Tyre size RR				205/55 R 17 95 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		

Steering wheel, Worn, Acceptable



Instrument panel, complete, Not functioning (well), Acceptable



Bonnet, Scratch(es), Polish



Bumper F, Scratch(es), Acceptable




Wing RL, Scratch(es), Polish



Door RL, Dent(s) and scratch(es), Spot repair



Step L, Scratch(es), Polish



Door FL, Scratch(es), Spot repair



Wing FL, Scratch(es), Polish




Charging cable (normal), Missing, Check



Rear light R, Scratch(es), Polish



Bumper R, Scratch(es), Polish




Rear light L, Scratch(es), Polish



Alloy rim FR polished, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable




Door RR, Dent(s) and scratch(es), Spot repair




Wing RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Roof, Dent(s), Acceptable



Bodywork, No damage, Acceptable

